

This appendix details equipment and supplies identified by Tetra Tech as necessary for the field activities described in this SAP:

Rental equipment:

6 battery-operated low-flow air pumps
Calibration for pumps (Dry-Cal?)
5 Trimble pro-XRS GPS units
5 digital cameras
6 Phones/radios (one for field office, one for each team)
Vehicles

Purchase/From Supplies:

2 laptop computers

Inspection:

10 clipboards
6 x 50-foot tape measures
Palette knives, etc. (for looking under insulation)
5 stepladders (for attic, barn inspections)
Scale bars for photographs
Field log books

Sampling:

¼-inch diameter plastic tubing
Pocket knives
Ziploc bags
Duct tape
Wet wipes
Waterproof permanent markers
15 x 100 cm² templates
20 x 25-cm rulers
10 x Trowels
6 x Stainless steel mixing bowls
Steel sampling spoons
Sample labels
Silica sand (asbestos-free) for soil field blanks
Secure shipment containers
Bubble wrap for cassette shipment
Trash bags

PPE:

Respirator for each asbestos inspector
Replacement particulate respirator cartridges
Vinyl/nitrile gloves, various sizes

Decon:

Paper towels
Bristle brushes
Water spray bottles
5-gallon buckets
Surfactant (Alconox)

Lab-supplied:

Microvacuum dust sampling cassettes
Chains of custody
Sample shipment security seals
Cassette lot blank samples

Field Forms:

IFFs
SCDCs
Verbal interview forms
Field audit forms